

## Office of the Chief Fire Officer, Bengaluru-East Zone, Karnataka Fire & Emergency Services, Commissariat Road, Bengaluru-560 025.



No. 317/CFO/Bng-East/FSR/2022

Dated: 07-03-2022

## ANNEXURE - B Group - B Educational Buildings

To,
The Director
M/s. Bangalore International Academy,
# 265/3, Samethanahalli, IOCL Road,
Opp. Soukya International Holistic Health Centre,
Whitefield Road,
Bangalore-560067.

Sir,

Sub: Issue of "Fire safety recommendation" to "M/s. Bangalore International Academy, # 265/3, Samethanahalli, IOCL Road, Opp. Soukya International Holistic Health Centre, Whitefield Road, Bangalore-560067" - reg.

Ref: 1) Your request letter dated: 04-03-2022.

2) Inspection report No: 09/DFO/MFS-Bng/FSR/20 dt:05/03/2022.

<<<>>>

With reference to the subject cited above, the premises of M/s. Bangalore International Academy, # 265/3, Samethanahalli, IOCL Road, Opp. Soukya International Holistic Health Centre, Whitefield Road, Bangalore-560067" was inspected by the District Fire Officer, Mahadevapura Fire Station, Bengaluru on 05-03-2022 with respect to Fire prevention, Fire fighting and Evacuation measures to be complied in the above premises and has submitted the details as under.

## Part-A. Details of the building / premises :-

01	Name and Address of the Applicant.	:	The Director M/s. Bangalore International Academy, #265/3, Samethanahalli, IOCL Road, Opp. Soukya International Holistic Health Centre, Whitefield Road, Bangalore-560067.
02	Name and Address of the premises.	;	M/s. Bangalore International Academy, #265/3, Samethanahalli, IOCL Road, Opp. Soukya International Holistic Health Centre, Whitefield Road, Bangalore-560067.
03	Name and address of the Building owner	:	Sri T Chandrashekar S/o Tippareddy, Hrudayalay Nilay Prashant Layout, Kodigehalk Bangalore-560067.

SANGALORE INTERNATIONAL ACADEMY

Bangalore Internation

h balli (Octord

Name and Associated		2				
04	Number of buildings	*	01 Building.			
05	Number of floors	:	Ground+03 upper floors.			
06	Floor-wise details of					
	Floor-wise details of occupancy:-					
	Ground floor	:	01 vice principal room, 01 director room, 0 admin office, 01 chairman chamber, 05 clas rooms & 03 toilets			
	1 <sup>st</sup> floor	:	11 class rooms 01 staff room & 02 toilets			
	2 <sup>nd</sup> floor	:	01, computer lab, 01 biology lab, 18 class rooms, & 02 toilets			
	3 <sup>rd</sup> floor		01 physics lab, 01 art lab, 10 class rooms & 03 toilets.			
07	Height of the building	:	13.80 mtrs.			
08	Site area	:	13,483.60 sq.mtrs			
09	Built-up area of each floor:-					
	Ground floor	:	1040.00 sq.mtrs			
	1 <sup>st</sup> floor	:	1040.00 sq.mtrs			
	2 <sup>nd</sup> floor	:	1040.00 sq.mtrs			
	3 <sup>rd</sup> floor	:	1040.00 sq.mtrs			
10.	Total built-up area	:	4,160.00 sq.mtrs			
11.	Surrounding properties:-					
	North(Front)	:	Abutting Soukya road			
	South(Rear)	:	School Hostel block			
	West(Left)	:	Vacant land			
	East(Right)	:	School play ground.			
12.	Set-back area available around the building :-					
	North(Front)	:	26.00 mtrs			
	South(Rear)	:	03.00 mtrs			
	West(Left)	:	05.00 mtrs			
	East(Right)	;	75.00 mtrs.			

GALORE INTERNATIONAL ACADEMY

CHAIRMAN



Prinicipal

Bangalore International Academy, Whitefield
No. 265/3, Sammethanahalli, IOCL Road,
Opp. Soukya International Holistic Centre,
Whitefield, Bangalore-568 66/.

Part-B. On inspection of this School premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view :-

\$I. No. (1)	Details (02)	Existing (03)	Recommendations (04)		
01.	Accessibility to the premises	The premises accessit mtrs wide Soukya rothern side.	Complied		
02.	No. of entrances	Two entrances & 01 6	Complied		
03.	Width of entry / exit	Entrances:08.20 mtrs Exit: 8.20 mtrs	Complied		
04.	Diesel generators.	Two DG.s of 62.5 KV capacity provided.	Complied		
05.	No. of staircases	Nos. of staircases	:	02 No.s	Complied
	available	Width of staircases	:	1.50 m	
		Width of treads	:	30cm	
		Height of risers	:	15cm	Vac. v
		Nos. of riser per flight	:	06 No.s	
		Height of handrails	;	1.00m	
		Head room clearance	;	2,80 m	
06.	No. lifts and capacity.	Nos. of lifts	:	01 No	Complied
		Capacity of lifts	;	08 persons	- 1
		OF Nos ABC powder	ext	inguishers	1 ABC type extinguisher
07.	Fire extinguisher	Of Nos. ABC powder extinguisher each of 04 kgs capacity have bee			of 5 kgs capacity & 1 CO2
	provided.				extinguisher of 4.50 kgs capacity at every 100.00
				Sq. Mtrs of the school	
					building and also near
					the DG yard
					transformer yard / make switch board.
				. 1	

Bengelur

Prinicipal

Bangalore International Trademy, Whiteful No. 265/3, Sammet Ahatti, IOCL Room Opp. Soukya International Holistic Gents Whitefield, Mannelore-566 Occ.

Scanned by TapScanner

		•	and the second s
		Public address System with two	Complied
08.	Public address	way communication facility has	
	system	been provided at each staircase	8
		landing with console at the control	
		room, located on the ground floor.	
		room, located on the ground	
		04 No.s hose reel hoses of 12mm	Complied
09.	First aid Hose reel	size and of adequate length to	
	hose.	reach farthest point of the floor	
		with shut off branch having nozzle	- 0
		of 5mm size has been provided.	
		Br Shill Size has a comp	
-	). Terrace tank over	Terrace tank of 10,000 ltrs water	
10	respective tower	. Landban provided	Complied
	terrace.		
		Booster pump capable of delivering	
1	At the terrace tank level with minimum		Complied
	pressure of 3.5	!	Compile
	kg/cm <sup>2</sup> .		
		The fire control room Provided at	
1	<ol><li>Fire control room at ground floor.</li></ol>	ground floor & All emergency	Complied
	groana noon	numbers displayed.	
-	3. Escape routes	Marked fire exit routes to guide	
1		Teachers/Students/staffs move to	Complied
		the safer places displayed.	
		Fire order board has been	
1	4. Fire order	fire order board has been displayed.	Complied
		displayed.	
	2 Laborated in ing	Not Trained.	40% of the
1	5. Fire fighting training		staffs/Teachers shall be
		·** :	got trained in fire
			prevention, fire fighting
	4	fig.	& evacuation at R.A.  Mundkur fire &
	from I	10.2 4 46 22 7	Midilakoi
			emergency service Academy, Bannerghatta
	1000	Alcer * SE	road, Bangalore-560 029.
		Salura Falura	W_
L		200/0	19.
	1,	\B \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \	pelalalnal

FOR BANGALORE INTERNATIONAL ACADEMY

Prinicipal
Bangalere International Academy, Whitefiel
No. 265/3, Sammethanahalli, IOCL Road
Opp. Soukya International Holistic Centre
Whitefield, Bangalere-560 067.

Under the circumstance stated above, there is No Objection to run education activity in your school building, subject to the condition of providing additional fire fighting equipments and fire precautionary measures shown in column No.4 of Part-B. Therefore, the management should comply Karnataka Fire & Emergency Services Department conditions to provide additional equipments and then intimate to this office within 90 days positively without fail. "This Fire safety recommendation Certificate valid for Only One Year from the date of issue and is renewable without fail".

All requirements recommended above are as per National Building Code-2016 Part-4 clause 3.1.3 of Fire and Life safety will have to be complled with mandatorily.

Seudannin \*

Yours faithfully,

Chief Fire Officer Bengaluru East Zone Bengaluru

Copy to the District Fire Officer, Mahadevapura Fire Station, Bengaluru.

FOI -ANGALORE INTERNATIONAL ACADEMY

CHARMAN

Prinicipal

Bangalore International Academy, W.
No. 265/3, Sammethanahalli-Toc

Opp. Soukya International Holistica
Whitefield, Bangalore-560 of